**BOREWELL COMPLETION REPORT**

# VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. : 1142

Date : 22/09/2020

1. Customer's Name and Address with Telephone No. : Assistant Executive Engineer BBMP Bangalore Yelahanka Sub-division Bangalore – 560064
2. Well Location : 96th main JP. Near Sugalalli Ranganna Park
3. Total Well Depth / Drilled in Ft. : 1250 ft.
4. Casing Erected in Ft. : 275 ft.
5. Water Struck at the Depth of :
6. Total Yield (Measuring method "V" Norch : 3" / Inches on "V" Norch)
7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear
8. At the Depth of :
9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

Party's signature

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬ.ಜ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-106

For VINAYAKA ENTERPRISES

Manager / Proprietor

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅ...
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾ...
ಬ.ಜ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-106

Smt. Kavitha Singh

Water Diviner

BOREWELL
BOREWELL
COMPLETION REPORT

# VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. : **1141**

Date : 22/09/2020

1. Customer's Name and Address with Telephone No. : Assistant Executive Engineer
BBMP Bangalore
Yelahanka Sub division
Bangalore - 560064
2. Well Location : Opp. 8th main IP. Opp. Iswara Deepikatha
3. Total Well Depth / Drilled in Ft. : 1350 ft.
4. Casing Erected in Ft. : 280 ft.
5. Water Struck at the Depth of :
6. Total Yield (Measuring method "V" Norch : 2.5" / Inches on "V" Norch)
7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear
8. At the Depth of :
9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

Party's Signature

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ
ಬ.ಬ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-೫೬

For VINAYAKA ENTERPRISES

Manager / Proprietor

Smt. Kavitha Singh

Water Diviner

BOREWELL COMPLETION REPORT

# VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. : 1143

Date : 22/09/2020

1. Customer's Name and Address with Telephone No. : Assistant Executive Engineer BBMP Bangalore Yelahanka Sub-Division Bangalore - 560064
2. Well Location : R-sector, Near BBMP Help point
3. Total Well Depth / Drilled in Ft. : 1500 to [illegible] mtrs
4. Casing Erected in Ft. : 225 ~~Mtrs~~
5. Water Struck at the Depth of :
6. Total Yield (Measuring method "V" Norch : 9" / Inches on "V" Norch)
7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear
8. At the Depth of :
9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

Party's Signature

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬ.ಬ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-106

For VINAYAKA ENTERPRISES

Manager / Proprietor

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬ.ಬ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-106

Smt. Kavitha Singh

Water Diviner